

Die Cast Lock Instructions

1. Insert cable into rectangular hole (designated by arrow).
Note: Be careful when handling the cable ends. if they're frayed, they can become very sharp.
2. Feed cable through the hole and into the second rectangular hole (also designated with arrow).
3. Press the lock to increase/decrease the size of the loop.
4. To remove cable, press the locks and pull the cable out (not shown).

